



14/11/2018

Dear Customer,

We would like to inform you that due to a specific problem in the production line, we are calling back and replace some of stainless steel electrodes.

The problem exists in several batches of stainless steel electrodes only:

|                |         |         |         |         |
|----------------|---------|---------|---------|---------|
| Z316L-2.50 mm  | PK77195 | PK77248 |         |         |
| Z312S-4.00 mm  | PK77197 | PK77003 | PK77119 |         |
| Z309MO-3.25 mm | PK77054 |         |         |         |
| Z309MO-4.00 mm | PK77056 |         |         |         |
| Z312S-2.50 mm  | PK76956 |         |         |         |
| Z312S-3.25 Mm  | PK77032 | PK76973 | PK77154 | PK77185 |
| Z316L-2.50 mm  | PK77248 |         |         |         |
| Z312SB - 3/32" | PK76945 | PK76942 |         |         |

The Batch number can be identified on the packaging in five digits after the PK letters.  
As always, we believe to the highest quality of our products and we are doing our utmost  
To supply highest quality to our customers

Kindest Regards  
**Export Department**